


65Tii40 Assembly under 2m



The GAI angle joiner has two holes to use as marking points to allow for easy mitre cutting.

Use a hacksaw with 32TPI blade to cut both stainless grate and stainless channel.
 NOTE, cut the GRATE AFTER the CHANNEL is ASSEMBLED to ensure the grate fits correctly.

Use Sika 11FC and primer 210 to seal and adhere the joins

After marking where cut is required, cut and join as shown.

