





65i40 Assembly (Kits over 2m)




The GAI angle joiner has two holes to use as marking points to allow for easy mitre cutting.



Use a hacksaw with 32TPI blade to cut both stainless grate and stainless channel.
NOTE, cut the GRATE AFTER the CHANNEL is ASSEMBLED to ensure the grate fits correctly.



Use Sika 11FC and primer 215 to seal and adhere the joins



After marking where cut is required, cut and join as shown.

